

Packet 1

Application version: 1.4.0-1



Active Licenses:

10 12 41 44 58 61 72 75 78 81 82 83 84 85 86 87 88 92 94 96 97

Module 10

Mazda 3rd generation (2012+)

Mazda: 1.5L, 2.0L, 2.5L SKYACTIV-G P5/PE/PY (Mazda3/CX5/6 SkyActiv Mitsubishi)
Mazda: 1.5L, 2.0L, 2.5L SKYACTIV-G P5/PE/PY (Mazda3/CX5/6 SkyActiv Denso)
Mazda: 2.5T SKYACTIV-G PY (Mazda CX9 SkyActiv Mitsubishi)
Mazda: 2.2L SKYACTIV-D 5H (Mazda3/CX5/6 SkyActiv Denso)
Mazda: 1.6L Z6 (Denso)
Reading, writing, checksum correction.

Module 12

Honda/Acura CAN-bus

Honda: Honda PGM-FI Generic Read-Only
Honda: Honda AT/CVT/DCT Generic Read-Only

PGM-FI (Keihin SH7058/1MB)
PGM-FI (Keihin SH72543/2MB)
PGM-FI (Keihin SH72546/3.75MB)
PGM-FI (Keihin MPC5566/3MB)
PGM-FI (Keihin TC1782/2.5MB)
PGM-FI (Keihin TC275/4MB)
PGM-FI (Keihin TC277/4MB)
AT/CVT/DCT (Keihin 512KB)
AT/CVT/DCT (Keihin 1MB)

PGM-FI (Matsushita SH7058/1MB)
PGM-FI (Matsushita SH72543/2MB)
PGM-FI 2013+ (Matsushita SH72543/2MB) (Test)
PGM-FI (Panasonic TC179X/4MB)
AT/CVT/DCT (Matsushita 512KB) (Test)

Honda: PGM-FI (Continental MPC5554/2MB)

PGM-FI (Hitachi SH7058/1MB) (Test)
PGM-FI (Hitachi SH7059/1.5MB) (Test)
PGM-FI (Hitachi SH72543/2MB)
PGM-FI (Hitachi MPC5554/2MB) (Test)
AT/CVT/DCT (Hitachi SH72531/1280KB)
AT/CVT/DCT (Hitachi SH725x3/2048KB)
Reading, writing, checksum correction.
UDCT (Continental TC1782/2.5MB)
Writing, checksum correction.

Module 41

Scania EMS S6

Scania EMS/EDC S6 250Kbps (MPC555)
Scania EMS S6 500Kbps (MPC555)
Reading, writing, checksum correction.

Module 44

Scania EMS S7/S8

Scania EMS S7 250Kbps (MPC563)
Scania EMS S8 250Kbps (MPC5566) - reading requires direct connection to the ECU
Scania EMS S8/EMD1 500Kbps (MPC5566) - reading requires direct connection to the ECU
Reading, writing, checksum correction

Module 58

Temic TCU

DQ200MQB/G2 (0CW)
DQ250MQB (0D9)
DQ400 (0DD)
Reading, writing, checksum correction

VL381/DL382 (0AW/0CK)
DL501/G2 (0B5)
DQ200 (0AM)
DQ250E/F (02E)
VL300/V30 (01J/0AN)
Writing, checksum correction

DQ200/MQB/G2 Boot (EEPROM)
DQ250E/F/MQB Boot (EEPROM)
DL501/G2 Boot (EEPROM)
VL381 Boot (EEPROM)
DL382 Boot (EEPROM)
Honda UDCT Boot (Continental TC1782/EEPROM)
DQ200/MQB/G2/DQ400 Boot (EEPROM)
Reading, writing

DQ200/MQB/G2 Boot (MICRO)
DQ250E/F/MQB Boot (MICRO)
VL381 Boot (MICRO)
DL501/G2 Boot (MICRO)
DQ500 (0BH/0BT)
VL300/V30 BSL (FLASH)
VL300/V30 BSL (EEPROM)
DQ250C (02E)
DL382 Boot (MICRO)
Honda UDCT Boot (Continental TC1782/MICRO)
DQ200/MQB/G2/DQ400 Boot (MICRO)
Reading, writing, checksum correction.

EDC DC0/DC4 Gen2 (DKG250 Gen2) Boot (TC1784/MICRO)
EDC DC0/DC4 Gen2 (DKG250 Gen2) Boot (TC1784/EEPROM)
VGS-FDCT Boot (TC1766/MICRO)
VGS-FDCT Boot (EEPROM)
VGS2-FDCT Boot (TC1784/MICRO)
VGS2-FDCT Boot (TC1784/EEPROM)
Reading, writing in service mode

Haval 7DCT450 Bootloader (EAST80.D1 TC265/MICRO) [Test]
Hyundai TAD801 D8F48W Bootloader (TC275/MICRO) [Test]
Reading, writing, checksum correction

Haval 7DCT450 Bootloader (EAST80.D1 TC265/EEPROM) [Test]
Hyundai TAD801 D8F48W Bootloader (TC275/EEPROM) [Test]
Reading, writing

Module 61

Kia/Hyundai CPGDSH/CPEGD

1.6L (CPGDSH2.24.1/CPEGD2.20.1/UDS)
1.6L (CPEGD3.20.1/CPEGP3.20.2/CPGPSH3.24.1/UDS) [Test]
1.6L (CPGPSH3.26.1/UDS) [Test]
Reading, writing, checksum correction.

1.4T, 1.6L (CPEGD2.20.3/CPEGD2.20.4/UDS) - requires direct connection to the ECU
1.0L, 1.2L (CPEGP2.10.1/CPGPSH2.14.1/UDS)
Reading, writing, checksum correction, unlocking

1.6L (CPEGD3.20.1/CPEGP3.20.2/CPGPSH3.24.1/UDS) [RD/WR/CK]
1.6L (CPGPSH3.26.1/UDS)
Reading, writing, checksum correction

CPEGD3/CPEGP3/CPGPSH3 CAN FD via Scanmatik 3

Module 72

Mazda Gen 4

1.5L, 2.0L, 2.5L SKYACTIV-G P5/PA/PE/PY MY2019 (Mitsubishi) [PYFA]
1.5L, 2.0L, 2.5L SKYACTIV-G P5/PA/PE/PY MY2019 (Denso) [PYFB]
Reading, writing, checksum correction.

1.5L SKYACTIV-G P5 (Mazda2 2019+ Mitsubishi) [PV10/PV11]
Writing, checksum correction.

Module 75

Ford Power Stroke

Ford Truck: 6.7L Power Stroke V8 (EDC17CP05) [BC3A]
Ford Truck: 6.7L Power Stroke V8 (EDC17CP05) [FC3A]
Ford Truck: 6.7L Power Stroke V8 (EDC17CP65) [JL3A]
Ford Truck: 3.0L Power Stroke V6 (EDC17CP65) [JL3A]
Ford Truck: 6.7L Power Stroke V8 (EDC17CP05) [DC3A/FC3A]

Reading, writing, checksum correction

Module 78

Subaru Gearbox

Melco CVT CAN-bus (1N83M/1552KH MH8111/1536KB MH5006/1024KB MH8104/512KB)
Reading, writing, checksum correction

Module 81

JLR Gearbox

ZF 6HP26/6HP28 TCM (MPC5xx/TC1766)
ZF 8HP70 TCM (SH725xx)
ZF 8HP45/8HP70 TCM (TC2xx)
ZF 9HP48 TCM (TC1782)
ZF 6HP28 Continental TCM (TC1766) [AH42-Ax]
AWF21 Freelander 2/Evoque TCM [Test]
Reading, writing, checksum correction.

ZF 9HP48 TCM EEPROM (TC1782)
ZF 6HP28 Continental TCM (TC1766) EEPROM [AH42-Ax]
Reading, writing.

Module 82

Bosch SH725XX TCU Bootloader
Direct connection to the ECU is required! Working with Tactrix OpenPort 2.0 is not supported!
Working with Scanmatik 2/PRO/Scanmatik 3, Dialink, Chipsoft, Mongoose, CarDAQ has been checked.

Bosch SH725xx TCU
Flash Reading, Writing, Checksum corrections

Bosch SH725xx TCU
EEPROM Reading, Writing, Checksum corrections

Module 83

VAG Bosch DQ380/DQ381/DQ500/ZF 8HP

DQ380/381/500 (0DE/0DL/0GC)
AL450/AL551/AL951 (0CM/0BK/0BL)
AL552/AL952 (0D5/0D6)
AL1000/AQ250/AQ450 (0C8/09G) UDS
AL420/AL600 (09L/09E) K-Line [Test]
AL420/AL600 (09L/09E) CAN TP2.0 [Test]

Virtual reading, writing, checksum correction

AL600/AL750/AQ250 (09D/09G) K-Line [Test]
AL750/AQ250 (09D/09G) CAN TP2.0 [Test]
Reading, writing, checksum correction

Module 84

VAG Delphi DCM6.2

1.4L, 1.6L, 2.0L TDI (DCM6.2)
Virtual reading, reading, writing, checksum corrections

Module 85

Ford Gearbox

6HP26 TCM
6HP26 TCM
5R110 TCM
6R50/6R140 TCM [BC3A]
6F55/8F40/10R80/10R140 TCM [HC3A/HL3A/JL3A/JX6A/LC4A]
8F40/10R80/10R140 TCM [K1GA/K2GA/LC3A/LK4A]
Reading, writing, checksum corrections

Module 86

China Gearbox

Changan Alsvin 5DCT (EAST80.51/SPC563M)
Chery CVT19 (EAST80.11/MPC553A)
Chery CVT18/CVT25 (EAST80.13/SPC563M)
Chery/Exeed VX 8AT 2023MY (Aisin 845AHA)
Virtual reading, writing, checksum correction

Changan Alsvin 5DCT Bootloader (EAST80.51/SPC563M)
Chery CVT25 Bootloader (EAST80.13/SPC563M)
Reading, checksum correction

Geely DSI 6AT
GAC 7Wlyd (ATDG-81-9.4)
Huanghai A8R50 (ATDG-81-9.4)
Changan DF733 (ATDG-81-9.4)
Reading, writing, checksum correction

Geely Coolray 7DCT330
Haval 7DCT450 (EAST80.D1)
Haval 7DCT300 (HYCET)
Virtual reading, reading, writing, checksum correction

Module 87

PSA DCM6.2

Citroen/Peugeot 2.0L HDi (DCM6.2A)
Citroen/Peugeot 2.0L HDi (DCM6.2C)
Reading, writing, checksum correction.

Module 88

Ford AdBlue

AdBlue REDCM (DCU17PC43) [KV6A]
Reading, writing, checksum correction.

Module 92

Bosch MD1/MG1 Bootloader

MD1/MG1 FLASH (SPC572L/SPC5777M/SPC58/TC275TP/TC277TP/TC298TP/TC299TP/TC387QP/TC399XP)
MD1/MG1 FLASH (SPC572L/SPC574K/SPC5777M/SPC58/TC275TP/TC277TP/TC298TP/TC299TP/TC387QP/TC399XP)
T93 SPC5888
Reading, writing, checksum corrections

MD1/MG1 EEPROM (SPC572L/SPC5777M/SPC58/TC275TP/TC277TP/TC298TP/TC299TP/TC387QP/TC399XP)
MD1/MG1 EEPROM (SPC572L/SPC574K/SPC5777M/SPC58/TC275TP/TC277TP/TC298TP/TC299TP/TC387QP/TC399XP)
Reading, writing

Note: Scanmatik 2 PRO or Dialink (partial support) is required. Work is only possible with ECUs with the old protection system (the implementation of the new one began in mid-2020).

Module 94

Aisin TCU Bootloader

Aisin SH705x TCU (FLASH)
Aisin D70F4019 TCU (FLASH)
Aisin R7F701204/R7F701215/R7F701216 TCU (FLASH)
Aisin R7F7012xx TCU (FLASH)
Reading, writing, checksum correction

Aisin SH705x TCU (EEPROM)
Aisin D70F4019 TCU (EEPROM)
Aisin R7F701204/R7F701215/R7F701216 TCU (EEPROM)
Aisin R7F7012xx TCU (EEPROM)
Reading, writing

Module 96

ZF TC1782/TC275/TC277 TCU Bootloader

Direct connection to the ECU required!

ZF TC1782/TC275/TC277 TCU (FLASH)
Reading, writing, checksum correction

ZF TC1782/TC275/TC277 TCU (EEPROM)
Reading, writing

Module 97

China AECS/LinControl

DAM15KR/EA15MR/SWC14M (LinControl LEC4AF)
DAM16KL (LinControl LEC4AP)
JAC 2.0T HFC4GA3 (LinControl LEC4AF)
Reading, writing

BAIC 1.5L R15C1 (AECS FC-34)
Changan 1.2L LJ469Q (AECS FC-34)
Changan 1.5L DAM15KL (AECS FC-34)
Dongfeng 1.5L L4A15Q6 (AECS FC-34)
Dongfeng/Fengxing 1.5T 4J15T (AECS FC-34)
Dongfeng/Fengxing 1.6L 4A92FR (AECS FC-34)
JAC 1.6L DAM16KL/HFC4GB3 (AECS FC-34)
JAC 1.8L, 2.0L, 2.0T LJ4A18Q6/LJ481Q/HFC4NA3 (AECS FC-34/FC-51)
Jinbei/SWM/Brilliance 1.5L SWC15M (AECS FC-34)
Jinlu/Jinlong 2.0L LJ481 (AECS FC-34)
King Long/Jinlong 1.8L LJ4A18 (AECS FC-34)
LDV/SAIC 1.5L LJ4A15 (AECS FC-34)
SGMW 1.8L, 2.0L LJ479Q6/LJM20B (AECS FC-34/FC-50)
Shandong Kama 1.6L DAM16KR (AECS FC-34)
Xiamen Golden Dragon 1.8L LJ4A18 (AECS FC-34)
JAC 1.5T HFC4GC1 (LinControl LEC4GD) [Test]
BAIC 1.6L LQ475QMB (AECS FC-50)
Chery 1.5L DAM15KR (AECS FC-34)
Foton 1.5L DAM15KL (AECS FC-34)

Reading, writing, checksum correction