



<div style="text-align: right;">AK</div> <div style="text-align: left;">Function</div>	<div style="text-align: center;">  AK-500 </div>	<div style="text-align: center;">  AK-400 </div>
Communications port	USB (2.0)	Serial port
Mercedes-Benz	Support W140/W203/W204/W208/W209/W210/W211/W211 Keyless go /W215/W219/W220/W220 Keyless go /W230/	Support W203/W208/W209/W210W215/W220/
BMW	Support for the new old 1/3/5/7/8/Z/M/ MPC (MPC555/556, MPC561/562, MPC563/564), external Flash (MB58BW016, 29BL802C, AM29BDD160, S29CD016, DE28F800 etc.) and external EEPROM (M95xxx). An advanced tool of car ECU repair and programming, odometer adjustment and key programming as well.	Support new 1/3/5/7 / key match

Audi	<p>Support</p> <p>MPC (MPC555/556, MPC561/562, MPC563/564), external Flash (MB58BW016, 29BL802C, AM29BDD160, S29CD016, DE28F800 etc.) and external EEPROM (M95xxx). An advanced tool of car ECU repair and programming, odometer adjustment and key programming as well.</p>	Do not support
VW	<p>Support</p> <p>MPC (MPC555/556, MPC561/562, MPC563/564), external Flash (MB58BW016, 29BL802C, AM29BDD160, S29CD016, DE28F800 etc.) and external EEPROM (M95xxx). An advanced tool of car ECU repair and programming, odometer adjustment and key programming as well.</p>	Do not support

Special features	Match and support function “Keyless Go” of Benz Infrared Key;	Do not support
	Support Benz Infrared keys lock and unlock for EIS+ESL+ESM , the leading technology all over the world;	Do not support
	Support Directly reading EEPROM for BENZ DAS(1995–1998)via OBD, can to unlock DAS when you lost all keys and DAS is locked;	Do not support
	Read and write the ESL of E/Class and C/Class via K_line, no need remove ESL;	Do not support
	Support Benz ECU' s flash(29F400 and 29F800) and generate key data directly, no need Renew Flash and Programming ECU, the leading technology all over the world;	Do not support

(1) Benz(R or W220) shift module
ISM and 722.9 gearbox ECU drive
authority;
(2) upgrade ESM read and write
EEPROM.

Do not support



(The photo shows the AK-500)